



# Locations Identified Contain Deteriorated Lead Based Paint On The A Side Of The Building

(not to scale)



# Locations Identified Contain Deteriorated Lead Based Paint On The D Side Of The Building



# PHOTOS OF COMPONENTS WHICH CONTAIN LEAD AT 300 EAST WASHINGTON BOULEVARD, LOS ANGELES, CA



PHOTO # 1  
# 5 A,R Column



PHOTO # 2  
# 6 A,R Deck Wall



PHOTO # 3  
# 8 A,C Column



PHOTO # 4  
# 9 A,R Handrail



PHOTO # 5  
# 9 A,R Handrail




PHOTO # 6  
# 9 A,R Handrail



# PHOTOS OF COMPONENTS WHICH CONTAIN LEAD AT 300 EAST WASHINGTON BOULEVARD, LOS ANGELES, CA




PHOTO # 7  
# 14 A,R Wood Wall



PHOTO # 8  
# 14 A,R Wood Wall



PHOTO # 9  
# 14 A,R Wood Wall



PHOTO # 10  
# 16 A,R Wall Cap



PHOTO # 11  
# 17 A,R Window Sill



PHOTO # 12  
# 18 A,R Window Casing



# PHOTOS OF COMPONENTS WHICH CONTAIN LEAD AT 300 EAST WASHINGTON BOULEVARD, LOS ANGELES, CA




PHOTO # 13  
# 15 A,R Downspout



PHOTO # 14  
# 19 A,R Header



PHOTO # 15  
# 20 A,R Header




PHOTO # 16  
# 22 A,C Wood Casing



PHOTO # 17  
# 23 A,C Wood Jamb




PHOTO # 18  
# 24 A,C Panel



# PHOTOS OF COMPONENTS WHICH CONTAIN LEAD AT 300 EAST WASHINGTON BOULEVARD, LOS ANGELES, CA



PHOTO # 19  
# 25 A,C Panel Sill



PHOTO # 20  
# 26 A,C Entry Casing



PHOTO # 21  
# 27 A,C Wood Wall



PHOTO # 22  
# 28 A,L Wood Wall



PHOTO # 23  
# 29 A,L Soffit



PHOTO # 24  
# 31 A,L Window Casing



# PHOTOS OF COMPONENTS WHICH CONTAIN LEAD AT 300 EAST WASHINGTON BOULEVARD, LOS ANGELES, CA




PHOTO # 25  
# 34 D,R Wood Wall



PHOTO # 26  
# 35 D,R Window Sill



PHOTO # 27  
# 40 D,R Vent Casing



PHOTO # 28  
# 41 D,R Sill



PHOTO # 29  
# 42 D,R Vent



PHOTO # 30  
# 43 D,R Foundation



# PHOTOS OF COMPONENTS WHICH CONTAIN LEAD AT 300 EAST WASHINGTON BOULEVARD, LOS ANGELES, CA



PHOTO # 31  
# 44 D,C Wood Wall



PHOTO # 32  
# 45 D,C Window Sill




PHOTO # 33  
# 46 D,C Window Casing



PHOTO # 34  
# 50 D,L Wood Wall



PHOTO # 35  
# 51 D,L Window Apron



PHOTO # 36  
# 52 D,L Window Sill



# PHOTOS OF COMPONENTS WHICH CONTAIN LEAD AT 300 EAST WASHINGTON BOULEVARD, LOS ANGELES, CA



PHOTO # 37  
# 53 D,L Window Casing



PHOTO # 38  
# 51, 52, 53 D,L Window Components



PHOTO # 39  
# 54 D,L Vent

(Intentionally Left Blank)

PHOTO # 40

(Intentionally Left Blank)


PHOTO # 41

(Intentionally Left Blank)

PHOTO # 42

## SIDE C

Locations Identified Contain Deteriorated Lead Based Paint  
(not to scale)





# PHOTOS OF COMPONENTS WHICH CONTAIN LEAD AT 300 EAST WASHINGTON BOULEVARD # 101, LA



PHOTO # 1  
# 46 A,C Kitchen Door Casing



PHOTO # 2  
# 52 A,L Kitchen Chair Rail



PHOTO # 3  
# 53 A,L Kitchen Baseboard



PHOTO # 4  
# 55 B,R Kitchen Window Sill



PHOTO # 5  
# 56 B,R Kitchen Window Casing



PHOTO # 6  
# 61 D,L Kitchen Cabinet Side



# PHOTOS OF COMPONENTS WHICH CONTAIN LEAD AT 300 EAST WASHINGTON BOULEVARD # 101, LA



PHOTO # 7  
# 71 C,L Bath Wall




PHOTO # 8  
# 72 C,L Bath Wall



PHOTO # 9  
# 73 D,L Bath Baseboard




PHOTO # 10  
# 74 D,C Bath Bathtub



PHOTO # 11  
# 77 C,R Bath Window Casing




PHOTO # 12  
# 79 B,C Bath Cabinet door and Shelf



## Locations Identified Contain Deteriorated Lead Based Paint

(not to scale)



# PHOTOS OF COMPONENTS WHICH CONTAIN LEAD AT 300 EAST WASHINGTON BOULEVARD # 208, LA



PHOTO # 1  
# 34 C,R Bath Baseboard



PHOTO # 2  
# 40 B,L Bath Baseboard



PHOTO # 3  
# 45 A,L Bath Bathtub



PHOTO # 4  
# 48, 49 A,C Kitchen Door Casing and Jamb




PHOTO # 5  
# 62 C,C Kitchen Tile Counter



PHOTO # 6  
# 63 C,C Kitchen Backsplash



## Locations Identified Contain Deteriorated Lead Based Paint



# PHOTOS OF COMPONENTS WHICH CONTAIN LEAD AT 300 EAST WASHINGTON BOULEVARD, # 204, LA



PHOTO # 1  
# 27, 28, 29 A,R Bath Door, Casing and Jamb



PHOTO # 2  
# 29 A,R Bath Door Jamb



PHOTO # 3  
# 31 B,C Bath Wall



PHOTO # 4  
# 34 C,C Bath Baseboard



PHOTO # 5  
# 38 A,L Bath Bathtub




PHOTO # 6  
# 40 C,R Bath Shelf Support



# PHOTOS OF COMPONENTS WHICH CONTAIN LEAD AT 300 EAST WASHINGTON BOULEVARD, # 204, LA




PHOTO # 7  
# 43, 44, 45 C,L Bath Window Components



PHOTO # 8  
# 46 C,C Bath Baseboard



PHOTO # 9  
# 48 A,C Kitchen Door Jamb




PHOTO # 10  
# 53 D,C Kitchen Baseboard




PHOTO # 11  
# 61, 62 Kitchen Tile Counter and Backsplash

(Intentionally Left Blank)

PHOTO # 12

# Location Identified Contains Deteriorated Lead Tile

(not to scale)





# PHOTOS OF COMPONENTS WHICH CONTAIN LEAD AT 300 EAST WASHINGTON BOULEVARD, # 310, LA



PHOTO # 1  
# 35 A,C Kitchen Counter Tile

(Intentionally Left Blank)

PHOTO # 4



PHOTO # 2  
# 47 A,C Bath Baseboard

(Intentionally Left Blank)

PHOTO # 5



PHOTO # 3  
# 48 C,C Bath Bathtub

(Intentionally Left Blank)

PHOTO # 6